

DEVELON

Remarketing Pre-Inspection Report

Pass

Satisfactory work ready,
50%+ component or cosmetic condition

Fail

Limited work ready, does not function,
or less than 50% component or cosmetic condition

Date	January 12 th , 2020
Inspector	Eric A. Olsen
Email	ericolsenjr@megz-machinery.co.com
Dealer	Megz Machinery Co.

Make	DOOSAN
Model	DL550-3
Model Year	2014
Hours	7,178.8
Serial Number	DWGCWLAQTD1010046

General/Cosmetic

	Pass	Fail	Notes
1. Body/Metal/Fiberglass	☒	☐	
2. Cab Glass	☒	☐	
3. Cab Mirrors/Worklights/Covers	☒	☐	
4. Steps/Ladders/Handrails	☒	☐	
5. Hood/Grill/Fenders	☒	☐	
6. Fuel Tank Condition	☒	☐	

Cab/Control System - Key On

	Pass	Fail	Notes
7. Seat/Armrests	☒	☐	
8. Seat Belt	☒	☐	
9. Air Conditioner/Heater	☒	☐	
10. Control Screen/Panel	☒	☐	
11. Gauges/Warning Lights	☒	☐	
12. Battery	☒	☐	
13. Travel Alarm	☐ N/A	☐	
14. Interior Lights Function	☒	☐	
15. Oil Pressure	☒	☐	
16. Steering Controls	☒	☐	
17. Brake Control/Park Brake	☒	☐	
18. Backup Alarm/Travel Alarm	☒	☐	
19. Hydraulic Controls	☒	☐	

Engine

	Pass	Fail	Notes
20. Prior to Start Oil Quality	☒	☐	
21. Blowby at Idle (Compression Kit)	☒	☐	
22. Cooling System Check for Leaks/Coolant Level	☒	☐	
23. Oil Leaks During Function Check	☒	☐	

Drivetrain/Powertrain

	Pass	Fail	Notes
24. Linkage (Tracks)	☐	☐	
25. Final Drives	☐	☐	
26. Front Axle (Wheel)	☒	☐	
27. Rear Axle (Wheel)	☒	☐	

Hydraulics

		Pass	Fail	Notes
28. Pumps		☒	☐	
29. Valves		☒	☐	
30. Hydraulic Tank		☒	☐	
31. Hoses		☒	☐	
32. Loader Lift Cylinder/Blade	☐ N/A	☒	☐	
33. Bucket Tilt Cylinder/Blade	☐ N/A	☒	☐	
34. Boom Lift Cylinder	☐ N/A	☒	☐	
35. Stick/Arm Cylinder		☐	☐	
36. Thumb Cylinder		☐	☐	

Linkage

		Pass	Fail	Notes
37. Loader/Lift Arm Condition		☒	☐	
38. Pin/Bushings Boom Base		☒	☐	
39. Pin/Bushings Boom to Stick		☒	☐	
40. Pin/Bushings Stick to Coupler/Bucket	☐ N/A	☒	☐	
41. Stick Condition		☒	☐	
42. Boom Condition		☒	☐	
43. Bed Hoist Cylinder		☒	☐	

Undercarriage

		Pass	Fail	Notes
44. Tire Tread +50% Remaining		☒	☐	
45. Link Height +50% Remaining		☐	☐	
46. Pad Width +50% Remaining		☐	☐	
47. Pads +50% Remaining		☐	☐	
48. Rollers +50% Remaining		☐	☐	
49. Sprockets +50% Remaining		☐	☐	
50. Idlers +50% Remaining		☐	☐	

Attachment

		Pass	Fail	Notes
51. Coupler Function	☐ N/A	☒	☐	
52. Bucket/Attachment Function	☐ N/A	☒	☐	
53. Bucket (Specify Below)	☐ N/A	☒	☐	

Type: Dosan Size: 7.0 YD

7 YD BOCE JRBAC

**Pictures of 4 corners of machine, 1 cab picture,
1 hour meter picture, and 1 control panel picture
should be provided with this report.**

DEVELON

Remarketing Pre-Inspection Report

©2023 HD Hyundai Infracore. All rights reserved. DEVELON is a brand of HD Hyundai Infracore; HD Hyundai Infracore is an affiliate of HD Hyundai.